


# HAND-OPERATED PRECISION PRESSURE GAUGE

MHA

<b>Description</b>	A piezo-resistive pressure sensor converts the input pressure into a digital electrical signal, which is displayed on the LCD. On-off switch is located at the side of the plastic housing.
<b>Media</b>	compressed air or non-corrosive gases
<b>Pneumatic connection</b>	P+: pos. pressure P-/P-: differential pressure, the higher pressure to be connected at P+ plug nipple up to 1 bar, sleeve with union greater than 1 bar, each for hose internal diameter of Ø 4 mm
<b>Voltage supply</b>	9 V battery, 2.5 mA, type 6F22, PP3 or similar
<b>Display</b>	max. ± 1999, 12 mm tall, black numbers, 3½-digit LCD display, low battery display at low voltage, red LED lights up at overpressure, then measurement is faulty
<b>Output signal</b>	optionally 0...1 V
<b>Zero point</b>	All devices have a potentiometer for rough adjustment of zero point at the side of the housing.
<b>Linearity</b>	see chart, optionally 0.2% FS
<b>Long-term stability</b>	< 0.1% FS per year at > 20 mbar,
<b>Temperature sensitivity</b>	see chart, at 0 to 50 °C / 32 to 122 °F
<b>Temperature range</b>	0 °C to 50 °C / 32 °F to 122 °F
<b>Material</b>	Housing: plastic
<b>Over-pressure</b>	max. ± 1999, 12 mm tall, black numbers, red LED lights up at overpressure, then measurement is faulty
<b>Hysteresis</b>	< 0.1% FS
<b>Repeatability</b>	< 2% FS per year at < 20 mbar
<b>Resolution</b>	see chart 0.05% FS
<b>Protection class</b>	IP 54



positive pressure, vacuum  
and differential pressure

Repeatability	Temperature error	Linearity error	Over-pressure	Measurement range	Order number	E*
% FS	% FS	% FS	max. bar	mbar/bar		

## Hand-operated gauge for compressed air, measurement of positive pressure, vacuum and differential pressure, with battery, 3½-digit display MHA

1.0	4.0	1.0	0.25	0 ... 1 mbar	MHA-A1
0.3	2.5	0.8	0.25	0 ... 2 mbar	MHA-A2
0.3	1.2	0.8	0.25	0 ... 5 mbar	MHA-A5
0.2	1.0	0.8	0.25	0 ... 10 mbar	MHA-B1
0.1	1.0	0.7	0.35	0 ... 20 mbar	MHA-B2
0.1	1.0	0.7	0.35	0 ... 50 mbar	MHA-B5
0.1	1.0	0.5	0.35	0 ... 100 mbar	MHA-C1
0.1	1.0	0.5	0.75	0 ... 200 mbar	MHA-C2
0.1	1.0	0.5	1.5	0 ... 500 mbar	MHA-C5
0.1	1.0	0.5	3.0	-1 ... 1 bar	MHA-V1
0.1	1.0	0.5	3.0	0 ... 1 bar	MHA-01
0.1	1.0	0.5	4.0	0 ... 2 bar	MHA-02
0.1	2.0	0.5	10	0 ... 8 bar	MHA-08
0.1	2.0	0.5	12	0 ... 10 bar	MHA-10
0.1	2.3 mbar	1 mbar	3.3	0.7 ... 1.1 bar <sub>abs</sub>	MHA-S1



Gauges

1385


14

## Special options, add the appropriate letter


linearity < 0.2% FS	from 100 mbar on	MHA- . . B
0-1 V output signal	at electrical connector	MHA- . . N
P <sub>a</sub> indication	< 20 mbar: indication P <sub>a</sub> > 20 mbar: indication kPa	MHA- . . P
zero point fine adjustment	in the front	MHA- . . E
deviant measurement range	to be indicated on order	MHA-XX

## Accessories, enclosed

protective bag	for belt attachment	MHT
----------------	---------------------	-----



MHA



connection diagram

\* Product group

Calibration or test chart: see chapter "Technical Information"

PDF CAD  
www.aircom.net



Order example:  
MHA-A1